

Oil Field Environmental Incident Summary

Incident: 20151015084906 **Date/Time of Notice:** 10/15/2015 08:49
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: SUN NOTCH 41-32TFH
Field Name: SAND CREEK **Well File #:** 30325
Date Incident: 10/13/2015 **Time Incident:** 16:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 153 **Rng:** 96 **Sec:** 32 **Qtr:**
Location Description: Spill on location and area of 50' X 50' adjacent to location

Submitted By: Tim Homiston **Received By:**
Contact Person: Tim Homiston
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	85	Barrels				

Description of Other Released Contaminant:

Fresh Water (Pond Water)

Inspected: **Written Report Received:** 8/5/2016 **Clean Up Concluded:** 10/13/2015

Risk Evaluation:

Low risk to environment

Areal Extent:

Spill on location and area of 50' X 50' adjacent to location

Potential Environmental Impacts:

No risk to environment

Action Taken or Planned:

Install flapper valve near check so isolation can be achieved

Wastes Disposal Location: No waste requiring recovery - Pond Water

Agencies Involved:

Updates

Date: 10/15/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of pond water, due to a pump leak, affected topsoil off the well pad according to the report. Further followup needed.

Date: 10/26/2015 **Status:** No Further Action Requested

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived at 10:20 AM. 41 degrees and sunny. Walked perimeter and area adjacent to the well pad. Vegetation looked healthy with no visible signs of stress. Tested soil conductivity to confirm water type; no sign of additional chlorides. No further followup required at this time.